

Skü

Feeler gauges and gauges

Metrology - Measuring - Marking-out

814.WH 814 - Screw pitch gauges



Content set: 4 - 4,5 - 5 - 6 - 7 - 8 - 9 - 10 - 11 - 12 - 13 - 14 - 16 - 18 - 19 - 20 - 22 - 24 - 25 - 26 - 28 - 30 - 32 - 34 - 36 - 38 - 40 - 48 - 60

Number of Blades: 55° cutting gauge + 29 blades

Thread Forms: Whitworth thread

[g]: 40